BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER ELECTRICAL

COMPLETION REPORT

1	Name of Work	Operation and Maintenance of stree light at Ward No.12 Shettyhalli, Sheetyhalli surrounding Area Package D-2 of Dasarahalli Zone
2	Sanctioned Estimate	Rs.26,44,000
3	Head of A/c which is chargeable	P-0300 (Replacement of Burnt bulbs)
4	Entrustment Order No. & Date	EE/ELE/DZ/WO/7/A/16-17, Date:23.11.2016 & EE/ELE/DZ/SWO/000018/18-19, Date:23.07.2018,
5	Name of Contractor	M/s VIJAYA LAKSHMI ASSOCITES
6	o. Time stipulated for p. Completion of Work	365 Days
7	b.Delay in execution of work	Not Applicable
8	Measurement recorded in	M.B No: 3405/19-20
		340476 TO 340477
9	Check Measurement of Asst.Exe.Engr/.Executive Engineer on	//2021
10	Name of the Office/Office in charge of the Work	Executive Engineer (Ele),Dasarahalli Zone
	a) Asst.Eng/Jr.Engineer	Mr.K.N.Babu Reddy
	b) Asst.Executive Engineer	Mr.Gurappa.Y.Doddamani. (Incharge EE)

Sanctioned Estimated Amount	Amount Claims as per actually vide as per Bills	DIFFERENCE		Remarks
		EXCESS	SAVINGS	
26,44,000/-	**6,87,074/-**	**-/-**	**-/-**	**Previous BR list enclosed**

Certified that the above has been completed within the stipulated time noted in the work order.

1. Certified that the contractor has delayed and completed the work for which necessary time has been recovered.
2. Certified that the above has been executed by the contractor satisfactorily in accordance with the specification as embedded in the agreement.

Assistant Engineer(Ele)
Dasarahalli Zone, BBMP

Assistant Executive Engineer(Ele)
Dasarahalli Zone, BBMP

Executive Engineer(Ele
Dasarahalli Zone, BBMP

Scanned by CamScanner